



Thermal Transfer Ribbon Recommendations

x = excellent/good rating

Facer	DNP					ITW			limak				
	TRX-50	TRX-55	R300	TR4085PLUS	M260	B220/W90	B128	B324	GP725	High Mark	Prime Mark	SP330	PM308
Type	wax/resin	wax/resin	resin	wax	wax/resin	wax/resin	wax/resin	resin	wax	wax	wax/resin	resin	wax/resin
008GB	x	x		x	x	x	x		x	x	x		x
020AC	x	x	x		x		x	x				x	x
020CL	x	x	x	x	x	x	x		x	x	x	x	x
020MY	x	x	x		x		x	x			x	x	
020PN			x					x				x	
021MU	x	x	x		x	x	x				x	x	x
022FC		x					x				x	x	
022FW		x					x				x	x	
023WP	x	x						x	x	x	x	x	
024TL	x	x	x	x	x	x	x		x	x	x	x	x
025PN			x					x				x	
026TL	x	x	x		x		x	x			x	x	
026TT		x	x	x	x		x			x	x	x	x
030MC	x	x			x	x	x				x	x	x
030TT	x	x	x		x	x	x	x			x	x	x
035WZ	x	x			x	x	x						
036CG	x	x					x				x	x	
036WG	x	x					x				x	x	
040PL		x			x	x							x
050HS	x	x		x	x	x	x		x	x	x		x
054SG		x			x	x							x
055BG	x	x		x	x	x							
055BS	x	x		x	x	x							
055DG	x			x	x	x							
055DS	x			x	x	x							
057HG		x			x	x	x		x	x	x		x
057MS	x	x		x	x	x	x						
060EG	x	x		x	x	x	x			x	x		x
060PG	x	x			x	x							
060PR	x	x		x	x	x	x		x	x			
060PS	x	x		x	x						x		
060SG		x		x	x	x	x		x	x			x
061DL		x		x	x	x			x				
075WP	x	x		x	x		x		x	x	x		x
095TK	x	x			x	x	x				x	x	x
0TTFA	x	x		x	x	x			x		x		x
0TTFP	x	x		x	x	x			x		x		x
100WP	x	x	x		x	x	x	x			x	x	x
1CLPT	x	x	x					x				x	
2VWPT	x	x	x	x	x	x	x	x	x	x	x	x	x
R60SG		x		x	x	x				x	x		x
VALUT	x	x		x	x	x	x		x	x	x		x

Due to the subjectivity of print, scratch, and smudge testing, ribbon end use testing is highly recommended to ensure all print criteria are being met.